CASE STUDY

Identifying Workmanship Issues with Factory Grade® Technology



Contractor Workmanship Feedback with IMCORP Factory Grade® Technology

HIGHLIGHTS

OVERVIEW

Workmanship issues are identified with the Factory Grade® technology.

CHALLENGE

Identifying root cause of substandard performance of joints in an efficient and effective manner.

RESULTS

Utility client partners with IMCORP to ensure quality and educate installers on how to identify defects with immediate evidence-based feedback before failure.

The Marson St	anufactur andards	ers'	
	Testing	Thresholds*	
Component Standard	Frequency	Sensitivity	Voltage
Terminations IEEE 48	50/60 Hz	5pC	≤ 1.5 Uo
Joints			
IEEE 404	50/60 Hz	5pC	≤1.5 Uo
Separable Connectors			
IEEE 386	50/60 Hz	5pC	≤1.3 Uo
MV Extruded Cable			
ICEA S-97/94-682/649	50/60 Hz	5pC	≤ 4.0 Uo^
HV / EHV Extruded Cable			
ICEAS-108-720	50/60 Hz	5pC	≤ 2.0 Uo
* No partial discharge should be obser threshold up to the voltage threshold	vable above the sensi	tivity	
^200 V/mil			

Table I: Manufacturers' Standards

[1] IEEE standards are classified as:

Standards: documents with mandatory requirements.

Recommended practices: documents in which procedures and positions preferred by the IEEE are presented.

• Standard Guides: documents in which alternative approaches to good practice are suggested but no clear-cut recommendations are made.

A utility requested IMCORP to commission a 750kcmil cable system at a new upscale subdivision as part of their medium voltage quality control program. Initial assessment with our Factory Grade® technology pinpointed 2 pre-molded joints on 2 phases that did not meet the accessory manufacturer's minimum performance standards. The first and second repair attempts by the original contractor crew were assessed only to find joints still failing to meet minimum performance standards. The installation contractor started questioning the validity of the assessment. The utility client was also under pressure from the developer of the residential subdivision to energize the circuit. Our client's construction supervisor requested our assistance with a field dissection and root cause analysis with the installation contractor in attendance.

Working with the manufacturer, installation contractor, and the utility client's engineer and construction supervisor, we directed the disassembly of the joints and identified several installation workmanship issues including, insufficient void filling grease, non-radial semicon cutbacks, insufficient connector crimping, improper application of the end caps, and an extreme bending radius near one of the joints. The workmanship issues were corrected and the joints were re-assembled. Our Factory Grade® technology then verified the entire cable system met the manufacturer's performance standards. This case is yet another example of IMCORP partnering with utility clients to ensure quality and educate installers on how to identify defects with immediate evidence-based feedback before failure.



Figure 1: Field disassembly of the premolded joints showed non-radial and jagged cutbacks (left) creating stress-enhancements. Evidence of insufficient void filling grease applied under the end caps on both sides of the joint body (right, yellow circle), creating large air voids between the two mating surfaces.